Doc No. 0418G25SD12 – Rev.01 www.LiutaioCES.com Page 1 of 16 FMEDA STUDY REPORT – APV ARRANGEMENT

The purpose of this SAMPLE document is to show in the public domain a typical FMDEA Study Report For a "<u>Actuator-Positioner-Valve</u>" (APV) arrangement, developed by:

FS

Functional Safety

LIUTAIO

"FUNCTIONAL SAFETY SERVICES"

For preparing this SAMPLE report, examples and public data of actuators, positioner and valves was used in combination with


LIUTAIO experience.

However, when this report is prepared for a CUSTOMER, only the authorized or provided information by CUSTOMER will be used, and the report **WILL NOT BE** part of the public domain

In practice, Valve VENDORs/Manufacturers consider as CONFIDENTIAL a document/report like this one. Information like this one **WILL NOT** be found in the public domain.

FS Functional Safety Maximum PFDayg	LIUTAIO - Consulting and Engineering Services	
	0418G25SD12 – Rev.01 www.LiutaioCES.com Page 2 o	f 16
SIL 2 SIL 3 SIL 4 FFD98 th	FMEDA STUDY REPORT – APV ARRANGEMENT	1 10
FS Functional Safety		
Maximum PFDavg	Table of Contents	5
SIL 1		
	ion and Stand ards	
	by Customer	
4.3 Document that WILL B	3E developed and delivered by LIUTAIO	4
5. Document LIABILITY		5
	e	
	itegy	
6.3 Description of "Target	System" under study	7
	" structure	
6.4 FMEDA analysis condit	tions and scenarios	8
6.5 FMEDA study results		11
APPENDIX A - "Actuator" FMEDA	table columns description	12
APPENDIX B - "Actuator" FMEDA	table for the analysis scenario No.1: "Fail Open" APV arrangement	
(Open to Trip), with FVST		14
	table for the analysis scenario No.2: "Fail Open" APV arrangement	
	table for the analysis scenario No.3 & 4: "Fail Open" APV arrangeme IT FVST, respectively	
(close to mp), with and withou	i rvsi, iespectively	10
12 3	V Q	
G		
6		
0.2		
	FS Functional Safe	ety
U	Maximum PFDavg	

FS	Functional Safety
	Maximum PFDavg
SIL 1	
SIL 2	



1. Document purpose

The purpose of this SAMPLE document is to show in the public domain a typical "<u>FMDEA Study</u> <u>Report</u>" developed by **LIUTAIO** "Functional Safety Services", for an "Actuator-Positioner-Valve" (APV) arrangement, as a requirement from a Customer (in this case, typically a Valve VENDOR/Manufacturer).

For preparing this SAMPLE report, examples and public data of actuators, positioner and valves was used in combination with **LIUTAIO** experience.

However, when this **report** is prepared for a CUSTOMER, only the authorized or provided information by CUSTOMER will be used, and the report **WILL NOT BE** part of the public domain.

In practice, Valve VENDORs/Manufacturers consider as CONFIDENTIAL a document/report like this one. Information like this one **WILL NOT** be found in the public domain.


2. Abbreviations

Refer to SAMPLE document: 0418D10SD01 Abbreviations

3. Glossary

Refer to SAMPLE document: 0418D10SD02 Glossary

		FS	Functional Safety
			Maximum PFDavg
		SIL 1 SIL 2	·/
		SIL 3	
Copyright © 2018 LIUTAI	O Consulting and E	ngineerin	ng Services



[P5] LIUTAIO – Functional Safety Services 0418G25SD11 FMEDA Background - Sample Document Rev.01

4.2 Documents provided by Customer

Not included in this SAMPLE document.

- 4.3 Document that WILL BE developed and delivered by LIUTAIO
- [D1] LIUTAIO Functional Safety Services 0418G25SD12 FMEDA study report - Sample Document (this document) Rev.01
- [D2] LIUTAIO Functional Safety Services 0418G25SD12 FMEDA assessment - Sample Document Rev.01
- [D3] LIUTAIO Functional Safety Services 0418G25SD14 Rev.01 APV Arrangement "SIL Certificate" - Sample Document Rev.01

FS	
	Maximum PFDavg
SIL 1	
SIL 2	
gineerin	g Services



Doc No. 0418G25SD12 – Rev.01 www.LiutaioCES.com Page 5 of 16 FMEDA STUDY REPORT – APV ARRANGEMENT

5. Document LIABILITY

LIUTAIO prepares FMEDA reports based on methodologies supported in International Standards. The used data is provided by Customer or from public and available databases and documental references.

Neither LIUTAIO, its employees, subcontractors, nor any person acting in LIUTAIO behalf makes any warranty, expressed or implied to any third party, with respect to the use of the information contained in this report or assumes any liability to any third party with respect to any use of the information.

LIUTAIO, its employees, subcontractors, and other assigns **CANNOT** individually, or collectively, predict what will happen in the future. **LIUTAIO** has made every reasonable effort to perform the work contained herein in a manner consistent with high professional standards. However, the quality of the work reported in this document is dependent on the accuracy of information provided by the Customer. The responsibility for use and implementation of the recommendations, designs, and procedures contained in this report rests entirely with the Customer.

6. FMEDA study

6.1 FMEDA study objective

An Actuator-Positioner-Valve (APV) arrangement shall be used as a final element in a "Safety Instrumented Function" (SIF).


It is required to issue the arrangement "SIL Certificate" to determine if the APV arrangement satisfies SIL-3 rating in fault tolerance 0 or 1 configuration.

This document is focused in developing the FMEDA study ONLY.

The document "<u>0418G25SD13 Rev.01 FMEDA assessment</u>" is focused in developing the FMEDA assessment, which includes the "SIL Certificate". "SIL Certificate" shall include for each FMEDA analysis scenario:

- Failure rates (LdSD, LdSU, LdDD & LdDU),
 - "Safe Failure Fraction" (SFF),
 - "Proof Test Effectiveness" (Et) or "Proof Test Coverage" (PTC), and
 - Satisfied "SIL rating" for fault tolerance 0 and 1 configuration.
 - PFDavg value for "Proof Test Period" of 1 and 2 years (1001).

FS	
	Maximum PFDavg
_	
SIL 1	
SIL 2	
SIL 3	



6.2 FMEDA execution strategy

The "FMEDA study" is a working session like HAZOP (Hazard and Operability Study).

In HAZOP session, members of the engineering disciplines involved in a process plant design, will identify plant "Hazards", failure modes and effects; and will define actions to reduce risk of identified hazards.

A "FMEDA study" is a working session conducted by a CHAIRMAN (LIUTAIO representative), where LIUTAIO and a Customer's multidisciplinary team will combine efforts to classify failure modes and effect as Dangerous/Safe failures, Detected/Undetected failures and distribution of component failure rates among failure modes.

LITUAIO HAS the expertise to perform the FMEDA study, **BUT** the Customer (Valve VENDOR/Manufacturer) involvement in the FMEDA study is required because ONLY the Customer DOES HAVE the expertise and detail know-how in the day to day design, manufacturing, installation and commissioning of industrial valves.


During the "FMEDA study" **LIUTAIO** will make emphasis in identifying "Fault detection capabilities" (Diagnostics) and "Safe Undetected Failures" of the APV arrangement, that will lead to improve this arrangement "Diagnostics" scope and SIL rating.

LIUTAIO will prepare the "FMEDA study report" to formally record all "FMDEA Study", decision notes and minute of meeting.

The "FMEDA study report" is the input to develop the "FMEDA assessment".

6.2.1 Failure classification that were used in this FMEDA study

Fail Safe	Failure that causes a "Target System" to move from the NORMAL to the SAFE state. Typically identified as a "Spurious Trip".
Fail Dangerous	Failure that prevents a "Target System" to fail on demand. In other words, when a HAZARD occurs, the "Target System" CANNOT perform its automatic protection function and it will remain in the NORMAL state.
Fail Detected	Failure in a "Target System" that can be "Detected" by an automatic diagnostic test, and this test implementation is capable to notify both a Safety/Control system and Operator. An automatic diagnostic test execution frequency MUST BE higher than a "Proof Test" execution frequency.
Fail UnDetected	Failure that CANNOT be "Detected" in a "Target System" by an automatic diagnostic test. Notification capability DOES NOT exist.
No Effect	Failure that has "NO Effect" in a "Target System" automatic protection function. In other words, failure that DOES NOT prevent a "Target System" to perform its automatic protection function and DOES NOT initiate "Spurious Trip".
Annunciation	Failure that has "NO Effect" in a "Target System" capability to perform its automatic protection function, BUT the "Target System" automatic diagnostic test stop to work.
0	In other words, this failure HAS NO impact in safety, BUT "Fault Detection Capabilities" (Diagnostics) WILL NOT work.
Fluid Leakage	Failure that causes a "Process Fluid" leakage in a "Target System".
Air Leakage	Failure that causes an "Air" leakage in a "Target System".



The Positioner is connected to "Control/Safeguarding system" to monitor de "Valve" position, and to notify Operator when a "Dangerous Detected" failure is revealed.

The APV arrangement installation **MAY** or **MAY NOT** include logic in "Control/Safeguarding system" to execute a "Full Valve Stroke Test" (FVST).

NOTE: Since the "Positioner" is monitoring the valve position, then when the valve moves **WITHOUT** command, the "Positioner" (or installed FVST) can notify Safety/Control System and Operator.

FS

In the APV arrangement:

- A dangerous failure in the "Actuator" will make the valve to fail on demand.
- A dangerous failure in the "Valve" will make the actuator to fail on demand.
- **BUT**, any kind of failure in the "Positioner" may lead to lose of the APV arrangement "Fault Detection Capabilities" only.
 - Copyright © 2018 LIUTAIO Consulting and Engineering Services

SIL 1 SIL 2

Functional Safety

FS

Doc No. 0418G25SD12 – Rev.01 www.LiutaioCES.com Page 8 of 16
FMEDA STUDY REPORT – APV ARRANGEMENT

6.3.1 "Target System" structure

In the "Target System", a Dangerous failure in the "Actuator" will make the "Valve" to fail on demand, and vice versa.

Figure 2 shows the "Target System" structure for FMEDA study in the form of a very simple "Reliability Block Diagram" (RBD). Notice that the "Positioner" **DOES NOT** appear in the RBD, because any kind of failure in the "Positioner" **WILL NOT** make the APV arrangement to fail on demand. The "Positioner" installation ONLY monitors the valve position, and it **HAS NO** effect in the APV operation.

It is a fact that a mechanical device **DOES NOT** include "Fault Detection Capabilities" (Diagnostics), unless it is combined with an electronic device that can monitor the mechanical device performance.

Some valves "SIL Certificates" declare "Safe Detected" and/or "Dangerous Detected" failure rate with other than ZERO(0.0) values, but they **DO NOT** indicate which electronic device is performing "Diagnostics" and which fails are monitored. It is IMPORTANT to indicate with electronic device will perform the mechanical device "Diagnostics".

NOTE: in some "Partial Valve Stroke Test" (PVST) applications the "Positioner" is capable to regulate the "Valve" position. ONLY in such cases, the "Positioner shall be included in the RBD.

Figure 2 – APV arrangement "Reliability Block Diagram"



Since any kind of failure in the "Positioner" **WILL NOT** make the APV arrangement to fail on demand, it **IS NOT** required to develop the FMEDA tables for this device.


6.4 FMEDA analysis conditions and scenarios

The way the APV arrangement fails in an operation/environment condition CAN CHANGE WHEN THE APV ARRANGEMENT is working in a different operation/environment condition.

Table 1 and Table 2 describe the operation/environment conditions which define the scope of work in this FMEDA study.

From Table 1 and Table 2, the analysis scenarios to consider in this study are:

- 1) "Fail Open" APV arrangement (Open to Trip), with FVST.
- 2) "Fail Open" APV arrangement (Open to Trip), NO FVST.
- 3) "Fail Open" APV arrangement (Close to Trip), with FVST.
- 4) "Fail Open" APV arrangement (Close to Trip), NO FVST.



YES

Not Applicable

Excluded

Excluded

Excluded

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

flow through

versa.

Below

Above

Below

atmospheric pressure

400°C (752°F)

-150°C (-238°F)

valve plug top to

bottom, or vice

Above 6.4 MPa

(64 Bar), or above ANSI CLASS 900

valve		Excluded		
Multi-Phase phase flow through valve	S	Excluded		
Broceller	General	High Pressure service		
Pressure	Operation	Low Pressure service		
Temperature.	General Operation 0-400°C (32-752°F)	High Temperature service Cryogenic service		
Daily temperature excursion (peak to peak)	10°C (50°F)			
Use of Hydraulic fluid to move valve actuator.	5	Excluded		
Use of Pneumatic fluid to move valve actuator.	YES			
Hydraulic Pneumatic or any other trin				

3

4

5

6 7

8

9

10

11

12

13

14

15

16

17

20

21

22 23 valve.

through valve.

General Liquid fluid passing through

Orientation installation of Fluid passing

General Gas fluid passing through valve.

Flow is flashing (vaporization) through

Single phase or steam flow through valve

Hydraulic package IS NOT included. Instrument Air system IS NOT included. Hydraulic, Pneumatic, or any other trip device to move the Actuator-Valve from Excluded NORMAL to SAFE state (Opened or Closed). Use of Electrical actuator to move valve. Excluded 18 Use of handwheel to move the valve. Excluded **19** Fail Close valve (Close to trip) Excluded YES Fail Open valve (Open to trip) Fail Close valve (Open to trip) Excluded Fail Open valve (Close to trip) YES Fail lock-in-last position valve Typically, double Excluded acting actuator

24 **24** Tight-Shutoff valve Excluded 25 FVST – Full Valve Stroke Test YES and NO 25 26 PVST – Partial Valve Stroke Test Excluded 26





Table 2 - Environment and site installation conditions to consider for APV arrangement FMEDA study

Á

STU 1	#	Environment/Site conditions	Included in study	Excluded from study	Remarks	#
51L 2	2	Surrounding Environment Temperature	0-40°C (32-104°F)		5	1
	2/	Surrounding Pressure	Atmospheric			2
	3	Typical field industrial installation at grade, or at Deck elevation.	YES			3
	4	APV arrangement is installed in Vertical or horizontal position	YES		9	4
	5	Dusty environment		Excluded	ľ	5
	6	Exposed to Elements / Weather condition changes	Moderate (Light r a in)		Heavy rain, Thunder (Lightning), Typhon, Tornado or Hurricane IS NOT included.	6
	7	Explosive/Inflammable area installation location	YES	N		7
	8	Outdoors installation location	YES			8
	9	Indoors @ Factory building		Excluded		9
	10	Sheltered installation location		Excluded		10
	11	Underwater installation location		Excluded		11
	12	Underground installation location		Excluded		12
	13	Humidity. Non-Condensing environment	YES		5-95% relative humidity	13
	14	Humidity. Condensing environment		Excluded		14
			No-Vibrations			15
	16	Solar radiation.	YES	6	Arrangement under shade in worst case.	16
	17	Electromagnetic interference		Excluded		17





6.5 FMEDA study results

As described in above section 6.3.1, in this SAMPLE document the "FMEDA study" shall be performed ONLY for the "Actuator" and "Valve" in the APV arrangement.

For both "Pneumatic Actuator" and "Gate Valve" data **IS NOT** available in the public domain.

NOTE: normally "Actuators" and "Valves" FMEDA data for a "FMEDA study" **IS NOT** available in the public domain. This information is considered CONFIDENTIAL by valve's VENDOR/Manufacturer.

For this SAMPLE document:

For "Gate Valve":

A public "SIL Certificate" from a "Gate Valve" VENDOR shall be used to develop the FMEDA assessment. See reference [D2]. No FMEDA tables will be developed.

See: <<u>PUBLIC GATE VALVE SIL CERTIFICATE></u> (Type A device)

For "Pneumatic Actuator":

Data from reference [P5] is used as an example to develop "Actuator" FMEDA tables. **LIUTAIO** experience was applied to analyse the data in order to produce a realistic result applicable for the "Target System" in this FMEDA study report.

The FMEDA study results are recorded in the "Actuator" FMEDA tables that are shown in the "<u>APPENDIX B</u>", "<u>APPENDIX C</u>" and "<u>APPENDIX D</u>" for the analysis scenarios No.1, No.2 and No.3/4, respectively. Refer to above section 6.3.1 for scenarios and conditions description.

"<u>APPENDIX A</u>" shows the FMEDA table columns description.


NOTE: Notice that as result of FMEDA study, the Failure effect between tables in "APPENDIX B/C" and "APPENDIX D" **ARE NOT** the same ones for the same Failure modes. This is an evidence that the APV arrangement behavior/performance **IS NOT** the same one in different scenarios.


NOTE: "Proof Test Effectiveness" (Et), or "Proof Test Coverage" (PTC), will be calculated with data from "Actuator" ONLY, because the FMEDA data from the "Valve" **IS NOT** available.

It is assumed that during FMEDA study session Customer presented "In House" failure data records. Base on this fact, it can be considered that the "Actuator" is a device "**Type A**".

Since both "Actuator" and "Valve" are "**Type A**" device and they perform in series (See RBD in section 6.3.1), then by applying "Route 1H" (IEC-61508-2 2010, section 7.4.4.2) the APV arrangement is "**Type A**" as well.

The FMEDA study report shall also include notes and a minute of meeting from the FMEDA study session, but that information is no included in this SAMPLE document.





		ALL	
convertent = 0.000	LIUTAIO Consulting	and Engineering Co	muico.
		and custoeening se	rvice


www.LiutaioCES.com Doc No. 0418G25SD12 - Rev.01 Page 14 of 16 FMEDA STUDY REPORT – APV ARRANGEMENT

APPENDIX B - "Actuator" FMEDA table for the analysis scenario No.1: "Fail Open" APV arrangement (Open to Trip), with FVST

FS Functional Safety

				L.												
		Project	SIL C	ertification SL1							Q				1	
		-		tor-Position <mark>er-V</mark> alve a	rrangement		-0				7.				1	
					ngement (Open to Trij	a) with F	VCT				<u>v</u>				+	
		Analysis Scenario	NU.1	- Fail Open APV and	ingement (open to Th	$\mathcal{F}_{\mathcal{F}}$, with r	v51.									
		P	^	D	F	-							54		1	
<u> </u>	4	В	С	D	E	F	G	H		-	K		M	N		
							-	-								
Car		6t		Failtune Maida	Fff a at	Comp	Failure	Failure		Diagnostics		Can "Proof	-			
Coi		Component	Qty	Failure Mode	Effect	Failure Rate[1/h]	Mode Ratio	Type D,S,#	Detected by Positioner	Detectable Ratio	Description	Test" reveal	SLf [m]	# - Other Failure classificaton	Notes	
п	-	description		description	description		95.0%		roomonor	Katio		00		Classification		4.
	1 1	Housing	1	Fracture Deflection	Torque transmission failure No effect	5.00E-09 5.00E-09	<u>95.0%</u> 5.0%		- 0				12 12	No Effect		1
	2	Housing cover	1	Fracture	Valve will not move	5.00E-09	95.0%						12			3
	-		1	Deflection	No Effect	5.00E-09	5.0%	#					12	No Effect		
	3 (Guide block assembly	1		Spring force will cause shutdown	3.00E-08	31.7%	S					12			
			1		Valve will not move	3.00E-08	31.7%	D		100.0%			12			
1			1	Fracture - middle	Valve will not move	3.00E-08	31.7%	D		100.0%			12	1		
			1	Deflection	No Effect	3.00E-08	5.0%	#					12	No Effect		8
	4	Extension rod assembly	1		Spring force will cause shutdown	5.00E-08	95.0%	S					12			9
			1		No Effect	5.00E-08	5.0%						12	No Effect		1
	5	Extension retainer nut assembly	1	Loss of Thread	Spring force will cause shutdown	5.00E-08	20.0%						12			1
			1	Loosen	Spring force will cause shutdown	5.00E-08	80.0%		×				12			1
	6	Yoke	1	Fracture	Valve will not move	1.00E-07	75.0%	D	Yes	80.0%		80.0%	12	Annunciation	Note 1	1
ļ			1	Deflection	Valve will be fully seated	1.00E-07	20.0%		Yes	80.0%		80.0%	12	Annunciation	Note 1	1
	- \	Value Die	1	Wear	Valve will be fully seated	1.00E-07	5.0%	D		0.0%			12			1
	7	Yoke Pin	1	Fracture Deflection	Valve will not move Valve not fully seated	6.00E-08 6.00E-08	95.0% 5.0%	D	Vee	0.0%			12	Annunciation	Note 4	1
	8 (Guide bar bearing	1	Excessive friction	No Effect	3.00E-08	40.0%		Yes	100.0%			12 12	No Effect	Note 1	1
	<u> </u>	Guide bai bearing	1	Excessive play	Valve will not move	3.00E-08	10.0%	#					12	No Effect		1
			1	Seized	Valve will not move	3.00E-08	50.0%	- # D					12			
	9 `	Yoke Pin bearing	1	Excessive friction	Process Safety Time may not be satisfied	3.00E-08	40.0%	D				50.0%	12			
			1	Excessive play	No Effect	3.00E-08	10.0%	#					12	No Effect		
			1	Seized	Valve will not move	3.00E-08	50.0%	D					12			
	10	Yoke/Guide block bushing	2		No Effect	3.00E-08	100.0%						12	No Effect		
		Yoke bearing	2		Process Safety Time may not be satisfied	3.00E-08	40.0%					50.0%	12			
			2	Excessive play	No Effect	3.00E-08	10.0%						12	No Effect		
			2	Seized	Valve will not move	3.00E-08	50.0%						12			
	12 (O-ring seal	2		N/A		99.0%						12	No Effect		
			2	Complete failure	N/A		1.0%						12	No Effect		
		Rod wiper	1	N/A	N/A		100.0%						12	No Effect		
	14 (O-ring seal	2	Leak	N/A		99.0%						12	No Effect		
	15	lanar and ach	2	Complete failure	N/A	2.505.00	1.0%		Vaa	E0.0%			12	No Effect	Note 1	
-	15	Inner end cap	1	Fracture Deflection	Air leak Air leak	2.50E-08 2.50E-08	95.0% 5.0%		Yes	50.0% 0.0%			12	Annunciation	Note 1	
	16	Tie bar	1	Fracture	Valve will not move	2.50E-08 2.50E-08	5.0%			0.0%			12 12			
	10	ne pal	2	Fracture	Release of pressure	2.50E-08	90.0%						12			
			2	Deflection	Valve will not move	2.50E-08	1.0%						12			
			2	Deflection	Release of pressure	2.50E-08	4.0%						12			
	17	Piston	1	Fracture	Spring force will cause shutdown	2.50E-08	95.0%			0.0%	0.0.1		12			
			1	Deflection	Valve will not fully seated	2.50E-08	5.0%		Yes	50.0%	Safety	50.0%		Annunciation	Note 1	4

NOTE 1 The Failure Mode-Effect becomes an "Annunciation" failure when the "Positioner" fails.






Doc No. 0418G25SD12 - Rev.01 www.LiutaioCES.com Page 15 of 16 FMEDA STUDY REPORT – APV ARRANGEMENT

APPENDIX C - "Actuator" FMEDA table for the analysis scenario No.2: "Fail Open" APV arrangement (Open to Trip), NO FVST

FS Functional Safety

				1	$1 \wedge 1 \wedge 1$											
		Droject	STI C	artification							0					
		_		ertification Sul			- 11									
				tor-Position <mark>er-V</mark> alve a			<u> </u>	7								
		Analysis Scenario	No.2 -	- "Fail Open" APV arra	angement (Open to Trij	o), NO F\	VST.									
		•		311.4												
	Δ	В	C	D	E	F	G	Ц			K		Μ	N		
	Α	В		D	E		9	п	•		n n	L .		IN		
								-	b	Diagnactica						
	Comm	Commonont		Failure Mode	Effect	Comp	Failure	Failure	Determinent	Diagnostics	,	Can "Proof	SLf	# - Other Failure		
	Comp	Component	Qty			Failure Rate[1/h]	Mode Ratio	Type D,S,#	Detected by Positioner	Detectable Ratio	Description	Test" reveal DU	[m]	classificaton	Notes	
1	ID	description Housing	1	description	description Torgue transmission failure	5.00E-09		D,3,#		Katio		00	12	Classificatori		-
1 2	1	Housing	1	Fracture Deflection	No effect	5.00E-09							12	No Effect		1 2
3	2	Housing cover	1	Fracture	Valve will not move	5.00E-09							12			3
4			1	Deflection	No Effect	5.00E-09		#					12	No Effect		4
5	3	Guide block assembly	1	Fracture - piston side power SW	Spring force will cause shutdown	3.00E-08		S					12			5
6	-		1	Fracture - spring side power SW	Valve will not move	3.00E-08		D					12			6
7			1	Fracture - middle	Valve will not move	3.00E-08		D					12			7
8			1	Deflection	No Effect	3.00E-08		#					12	No Effect		8
9	4	Extension rod assembly	1	Fracture	Spring force will cause shutdown	5.00E-08		S					12			9
10			1	Deflection	No Effect	5.00E-08		#					12	No Effect		10
11	5	Extension retainer nut assembly	1	Loss of Thread	Spring force will cause shutdown	5.00E-08							12			11
12			1	Loosen	Spring force will cause shutdown	5.00E-08		S					12			12
13	6	Yoke	1	Fracture	Valve will not move	1.00E-07	75.0%					80.0%	12			13
14			1	Deflection	Valve will be fully seated	1.00E-07	20.0%					80.0%	12			14
15	_		1	Wear	Valve will be fully seated	1.00E-07	5.0%						12			15
16	7	Yoke Pin	1	Fracture	Valve will not move	6.00E-08						-	12			16
17		Quide her hearing	1	Deflection	Valve not fully seated	6.00E-08 3.00E-08		D					12	No Effect		17
18 19	Ö	Guide bar bearing	1	Excessive friction Excessive play	Valve will not move	3.00E-08		#					12 12	No Effect No Effect		18 19
20			1	Seized	Valve will not move	3.00E-08		# D					12			20
21	9	Yoke Pin bearing	1	Excessive friction	Process Safety Time may not be satisfied	3.00E-08						50.0%	12			21
22			1	Excessive play	No Effect	3.00E-08	10.0%	#					12	No Effect		22
23			1	Seized	Valve will not move	3.00E-08		D					12			23
24	10	Yoke/Guide block bushing	2	Tear	No Effect	3.00E-08	_							No Effect		24
25	11	Yoke bearing	2	Excessive friction	Process Safety Time may not be satisfied	3.00E-08						50.0%	12			25
26			2	Excessive play	No Effect	3.00E-08							12	No Effect		26
27			2	Seized	Valve will not move	3.00E-08							12			27
28	12	O-ring seal	2	Leak	N/A		99.0%							No Effect		28
29			2	Complete failure	N/A		1.0%						12	No Effect		29
30		Rod wiper	1	N/A	N/A		100.0%							No Effect		30
31	14	O-ring seal	2	Leak	N/A		99.0%						12	No Effect		31
32			2	Complete failure	N/A		1.0%						12	No Effect		32
33	15	Inner end cap	1	Fracture	Air leak	2.50E-08							12			33
34	40	Tie bar	2	Deflection	Air leak	2.50E-08 2.50E-08							12			34 35
35 36	16		2	Fracture Fracture	Valve will not move Release of pressure	2.50E-08 2.50E-08							12 12			35
36		1	2	Deflection	Valve will not move	2.50E-08 2.50E-08							12			36
38			2	Deflection	Release of pressure	2.50E-08							12			38
39	17	Piston	1	Fracture	Spring force will cause shutdown	2.50E-08							12			39
40			1	Deflection	Valve will not fully seated	2.50E-08			FS FU		Safety	50.0%	12			40
													. –			

Copyright © 2018 LIUTAIO Consulting and Engineering Services





Doc No. 0418G25SD12 - Rev.01 www.LiutaioCES.com Page 16 of 16

FMEDA STUDY REPORT – APV ARRANGEMENT

APPENDIX D - "Actuator" FMEDA table for the analysis scenario No.3 & 4: "Fail Open" APV arrangement (Close to Trip), with and WITHOUT FVST, respectively.

FS Functional Safety

										o	0			, . est est	-	
		Drojost	CTL C	artification							0					
				ertification Sul			-									
				tor-Position <mark>er-V</mark> alve a			<u> </u>	2								
		Analysis Scenario	No.3	& 4 - "Fail Open" APV	arrangement Close to	Trip), w	ith and	WITH	OUT FVS	T, respect	ively					
		-	vsis Scenario No.3 & 4 - "Fail Open" APV arrangement Close to Trip), with and WITHOUT FVST, respectively													
							C									
Γ	Α	В	С	D	E	E S	G	Н			K		Μ	N		
L				5	-	· · ·			•			-				
						0.0				Diagnostics						
Г	Comp	Component		Failure Mode	Effect	Comp Failure	Failure Mode	Failure Type	Detected by	Detectable		Can "Proof Test" reveal	SLf	# - Other Failure		
	-		Qty			Rate[1/h]	Ratio	D,S,#	Positioner	Ratio	Description	DU	[m]	classificaton	Notes	
	ID	description		description	description Torque transmission failure					Idelo		00		classification		4.
1 2	1	Housing	1	Fracture Deflection	No effect	5.00E-09 5.00E-09							12	No Effect		2
3	2	Housing cover	1	Fracture	Valve will not move	5.00E-09							12 12			3
4	2		1	Deflection	No Effect	5.00E-09							12	No Effect		4
5	3	Guide block assembly	1		Valve will not move	3.00E-08							12			5
6	Ū		1		Valve will not move	3.00E-08					-		12			6
7			1	Fracture - middle	Valve will not move	3.00E-08							12			7
8			1	Deflection	No Effect	3.00E-08							12	No Effect		8
9	4	Extension rod assembly	1	Fracture	Valve will not move	5.00E-08		D					12			9
10		· · · ·	1	Deflection	No Effect	5.00E-08	5.0%	#					12	No Effect		10
11	5	Extension retainer nut assembly	1	Loss of Thread	Valve will not move	5.00E-08		D					12			11
12			1	Loosen	Valve will not move	5.00E-08							12			12
13	6	Yoke	1	Fracture	Valve will not move	1.00E-07						80.0%	12			13
14			1	Deflection	Valve will be fully seated	1.00E-07						80.0%	12			14
15			1	Wear	Valve will be fully seated	1.00E-07							12			15
16	7	Yoke Pin	1	Fracture	Valve will not move	6.00E-08							12			16
17 18	0	Guide bar bearing	1	Deflection Excessive friction	Valve not fully seated No Effect	6.00E-08 3.00E-08							12 12	No Effect		17 18
19	0	Guide bar bearing	1	Excessive flay	Valve will not move	3.00E-08							12	No Effect		10
20			1	Seized	Valve will not move	3.00E-08							12			20
21	9	Yoke Pin bearing	1	Excessive friction	Process Safety Time may not be satisfied	3.00E-08						50.0%	12			21
22			1	Excessive play	No Effect	3.00E-08	10.0%	#					12	No Effect		22
23			1	Seized	Valve will not move	3.00E-08							12			23
24	10	Yoke/Guide block bushing	2	Tear	No Effect	3.00E-08	100.0%	#					12	No Effect		24
25	11	Yoke bearing	2	Excessive friction	Process Safety Time may not be satisfied	3.00E-08			1 12			50.0%	12			25
26			2	Excessive play	No Effect	3.00E-08								No Effect		26
27			2		Valve will not move	3.00E-08							12			27
28	12	O-ring seal	2	Leak	N/A		99.0%							No Effect		28
29			2		N/A		1.0%							No Effect		29
30		Rod wiper	1	N/A	N/A		100.0%							No Effect		30
31	14	O-ring seal	2	Leak Complete failure	N/A N/A		99.0% 1.0%							No Effect No Effect		31
32 33	15	Inner end cap	2	Fracture	Air leak	2.50E-08							12 12			32 33
33 34	15		1	Deflection	Air leak	2.50E-08							12			33
35	16	Tie bar	2	Fracture	Valve will not move	2.50E-08							12			35
36	10	no sui	2	Fracture	Release of pressure	2.50E-00							12			36
37			2	Deflection	Valve will not move	2.50E-08			1				12			37
38			2	Deflection	Release of pressure	2.50E-08							12			38
39	17	Piston	1	Fracture	Valve will not move	2.50E-08			EG E		6-6-		12			39
40			1	Deflection	Valve will not fully seated	2.50E-08			FS FU		Salety	50.0%	12			40

Copyright © 2018 LIUTAIO Consulting and Engineering Services

M N
